



005230*1E328E00

FIG. 1 PRIOR ART



665280-1282860






FIG. 4




FIG. 5





FIG. 6






FIG. 7




FIG. 8

00302834-00000000

FIG. 9

FIG. 9 is a cross-sectional view of a device. A substrate 60 is shown at the bottom, with a layer 106 on top of it. A series of vertical structures 120 are formed on the surface of layer 106. Each structure 120 has a base 122. A layer 126 is deposited over the structures 120. A wedge-shaped structure 124 is positioned above the structures 120, with a vertical line 126 passing through its center. A small wedge-shaped structure 134 is shown to the right of the main structures 120, with an arrow pointing towards it. A layer 130 is located between the structures 120 and the layer 126.




FIG. 11




FIG. 12




FIG. 13

00382834, 002599




FIG. 14





FIG. 15

00302034-002500

FIG. 16



**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☒ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☒ **FADED TEXT OR DRAWING**
- ☐ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☒ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☐ **OTHER: _____**

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.